

MANUFACTURER	STORAGE	DISPOSAL FROM DATE OF 1 ST USE <i>Date of first use must be recorded</i>	DESTRUCTION REGARDLESS OF USE
Pamenter Petrie	2 years	5 years subject to interim inspection	<i>Destroy after 7 years regardless of use</i>
Ridgegear	10 years	5 years subject to interim inspection	<i>Destroy after 10 years regardless of use</i>
Spanset	2 years	Obsolescence is 5 years from date of first use	<i>Destroy after 7 years regardless of use</i>
Tractel	10 years	5 years subject to interim inspection	<i>Destroy after 10 years regardless of use</i>
Sala		Obsolescence is 5 years from date of manufacture and includes storage	<i>Destroy after 5 years regardless of use</i>
Miller Dalloz	10 years	5 years subject to interim inspection	<i>Destroy after 10 years regardless of use</i>
Willen's		Obsolescence is 5 years from date of manufacture and includes storage	<i>Destroy after 5 years regardless of use</i>

SAFETY HARNESS AND WEBBING PRODUCTS STATEMENTS OF OBSOLESCENCE

Following recent tests and evaluation of wear and acceptable life on a variety of safety harness's and associated webbing and fibre products. The PSMA are issuing guidance on acceptable life spans for member's respective products as part of its commitment to improving safety for work at height and in confined spaces.

The recommendations detailed above should be viewed as minimum guidance, **ALL PRODUCT** should be regularly inspected by a competent person and any product showing signs of excessive wear or material damage should be removed from service immediately and destroyed. It is essential that the product should have a traceable identifying mark and a recorded inspection history, if this is not visible, the product should be removed from service and destroyed.

This information is also available at www.cssworksafe.com the PSMA website and the HSE website.